



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt
Governor

Kathleen Clarke
Executive Director

Lowell P. Braxton
Division Director

1594 West North Temple, Suite 1210

PO Box 145801

Salt Lake City, Utah 84114-5801

801-538-5340

801-359-3940 (Fax)

801-538-7223 (TDD)

October 29, 1999

TO: Minerals File

FROM: Lynn Kunzler, Reclamation Specialist 

RE: Site Inspection, All Gypsum Corp., Dry Creek Mine, S/021/026, Iron County, Utah

Date of Inspection: October 13, 1999
Time of Inspection: 7:00 am
Conditions: Warm and Clear
Participants: Lynn Kunzler and Doug Jensen, DOGM

Purpose of Inspection: Document site conditions

There has not been much change from last site visit, no apparent activity for several weeks as indicated by large amount of russian thistle on pad and access road. Possible activity near north end by switchback and on east side of quarry. Site appeared to be stable. Topsoil stockpile has not been moved. However, no evidence of any addition losses due to its proximity to the drainage. Not much has been done with the drainage to the west of the pad. However, evidence indicates that no runoff breached the berm and entered the disturbed area of the pad.

Photos were taken to document site conditions.

jb
s21-26.ins



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt
Governor

Kathleen Clarke
Executive Director

Lowell P. Braxton
Division Director

1594 West North Temple, Suite 1210

PO Box 145801

Salt Lake City, Utah 84114-5801


801-538-5340

801-359-3940 (Fax)

801-538-7223 (TDD)

October 29, 1999

TO: Minerals File

FROM: Lynn Kunzler, Reclamation Specialist 

RE: Site Inspection, Morrill Nielson, Rose #1 Mine, S/041/026, Severe County, Utah

Date of Inspection: October 13, 1999

Time of Inspection: 4:30 pm

Conditions: Warm and Clear

Participants: Lynn Kunzler and Doug Jensen, DOGM

Purpose of Inspection: Operator requested inspection to close file

This site is in an area that is surrounded by historical mining activity. The file indicated that the disturbance created by this notice had been reclaimed and that future claim work would be done with hand tools only.

The access road had a fair stand of vegetation that equaled the surrounding undisturbed areas. It appeared that all recent mining disturbance had been successfully reclaimed.

This file can be closed.

Photos were taken to document site.

jb
s41-26.ins